




Weekly Tech Tip


Topic: Display States


June 28, 2010

In SolidWorks 2010, you can now create display states in a part file in order to look at different visual representations of a part. To create a display state, right click on empty space in the configuration manager, and choose 'Add Display State'. Thereafter, you can adjust certain attributes (such as color and transparency) for each display state.

Example of a part with 3 display states:







For Tech support please email techsupport@rnd-tech.com